



Recovery Spreadsheet.pdf

File	Sheet name	Color	Pieces	Order
Card10	Reference			
Card10a	Divider wall	Zinc Green	11	8
Card11	Stringers (3 sheets)	Med Gray	51	11
Card15	Transition strips	Med Gray	14	
Card15a	Recovery Flange, parts	Base Gray	12	9
Card14	Upper flange	Base Gray	5	
Card15	Lower ring	Base Gray	13	1
Card16	Upper ring	Base Gray	20	2
Card17	Parts		12	
Card17a	Teflon strips	White	8	8
Card18	Inner wall	Base Gray	1	3
Card18a	Home, Wall stringers	Med Gray	18	5
Card18b	Inner stringer support	Base Gray	2	7
Card18c	Transition stringer	Zinc Green	12	
Card19	Inner Wall	Base Gray	1	4
Card20	Marking Guide	White	1	
Card21	Forward Bulkhead		8	13
Card21a	Shrinkie parts		17	15
Card21b	Hatch Champ ring	Dark Gray	8	14
Card22	Forward Bulkhead		14	12
Card23b	Escape hatch parts		20	
21		Total	244	

These are the PDF files in the recovery folder. They are all needed to build the recovery compartment per the instructions in the recovery folder. The order is a rough order of when the sheet is used when following the given instructions.

Some of the parts for the escape hatch are missing. I lost the files. I'll add them later.

